

Michael O. Leavitt

Governor

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Date of Last Inspection: 12/1/99

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

Lowell P. Braxton 801-359-3940 (Fax)

Division Director 801-538-7223 (TDD)

Partial: Complete: XXX Exploration: Inspection Date & Time: 1/11/2000 / 10:00a.m.-3:00p.m.

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007						
Permittee and/or Operator's Name: Consolidation Coal Company						
Business Address: P.O. Box 566, Sesser, Illinois 62884						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Steve Behling						
State Officials(s): Bill Malencik Federal Official(s): None						
Weather Conditions: Raining						
Existing Acreage: Permitted- <u>950</u> Disturbed- <u>7</u> Regraded- <u>Seeded-</u> Bonded- <u>7</u>						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_Liability 1986 Year)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	$\overline{\Box}$	[]	[]
2.	SIGNS AND MARKERS	XX			\Box
3.	TOPSOIL	[]	$\overline{[XX]}$		
4.	HYDROLOGIC BALANCE:	. — —			
a.	DIVERSIONS	[XX]	\Box	[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS		[XX]		$\overline{\square}$
c.	OTHER SEDIMENT CONTROL MEASURES	$\overline{[XX]}$		\Box	\Box
d.	WATER MONITORING	$\overline{[XX]}$	\Box	[XX]	
e.	EFFLUENT LIMITATIONS		$\overline{[XX]}$		\Box
5.	EXPLOSIVES	$\overline{\square}$	[XX]	$\overline{\square}$	$\overline{\Box}$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]		$\overline{\Box}$	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	Ш	\Box	\Box
8.	NONCOAL WASTE	$\overline{[XX]}$	$\overline{\Box}$	[XX]	\Box
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	[XX]	\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE	[XX]	П	. 🗀	\Box
11.	CONTEMPORANEOUS RECLAMATION	[XX]	Ш	\Box	
12.	BACKFILLING AND GRADING	[XX]	Ш	\Box	\Box
13.	REVEGETATION	[XX]	$\overline{\square}$	\overline{XX}	\Box
14.	SUBSIDENCE CONTROL	ĪĪ	$\overline{[XX]}$		\Box
15.	CESSATION OF OPERATIONS	$\overline{[XX]}$	Ш	\Box	\Box
16.	ROADS:	· ——			
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	.Ll	[XX]	\Box
b.	DRAINAGE CONTROLS		$\overline{\square}$	Ш	Ll
17.	OTHER TRANSPORTATION FACILITIES		[XX]	$\overline{\Box}$	\Box
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\overline{[XX]}$		$\overline{\square}$	ΙΙ
19.	AVS CHECK (4th Quarter-April, May, June)(date)		\Box	\Box	$\overline{\Box}$
20.	AIR QUALITY PERMIT	$\overline{\Box}$	$\overline{[XX]}$	口	$\overline{\Box}$
21.	BONDING & INSURANCE	$\overline{[XX]}$	$\overline{\Box}$	\overline{XX}	$\overline{\Box}$

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 1/11/2000

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

The general area including the mine received the first moisture in the form of rain. It rained most of the day.

No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires water monitoring at high and low flow. The sampling on Ivie Creek above and below the mine are to be taken in May and September. The last sampling was taken September 21, 1998. The May sample has been taken. The company is working with the Division to submit automated data.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no significant noncoal waste, pop cans, etc. were observed during the instant inspection.

13. REVEGETATION

Seedlings we observed from last years rehabilitation efforts. The seedlings are most numerous in the regraded depression areas. The most significant change in the vegetation is the annual plants have completed their life cycle. The perennials are all still green. As a result, the perennials are more predominate and appear to occupy the lower areas very well.

16a. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

Emery County repaired the county road into and out of the permitted area. The work consisted of repairing the drainage across the road. Also, some bumps were repaired.

21. BONDING AND INSURANCE

Insurance expires 11/5/99. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: <u>Tim Kirschbaum (Consol)</u> <u>Henry Austin (OSM)</u>
Given to: <u>Pam Grubaugh-Littig (DOGM)</u> Filed to: <u>Price Field Office</u>

Date: January 21, 2000

Inspector's Signature: #26

Wm. J. Malencik